

OCK-10

Optical Cleaning Kit



Key Features

- Complete set of tools for connector cleaning and maintenance to ensure all measurements are done in the best conditions
- Robust field carrying case
- Keep your optical connectors at their best for inspection, maintenance and troubleshooting networks
- An essential kit at a very reasonable price

To improve and assist fiber optic connection performance optical connectors need to remain clean. Fiber end surfaces need inspecting and cleaning prior to being placed in service.

The SMART optical handhelds range offers a brand new cleaning kit - the OCK-10 Optical Connector Cleaning Kit as part of its range of essential accessories to maintain your handhelds performance.

The OCK-10 is a complete set of cleaning tools in a robust case for field service.

Ordering Information

BN 2229/90.21	OCK-10
	Optical Connector Cleaning Kit consisting of:
	3× cleaning paper
	5× cleaning sticks
	1× cleaning tape
	1× spare tape for optical cleaning tape
BN 2229/90.07	Optical cleaning tape
BN 2229/90.08	Spare tape for optical cleaning tape

All statements, technical information and recommendations related to the products herein are based upon information believed to be reliable or accurate. However, the accuracy or completeness thereof is not guaranteed, and no responsibility is assumed for any inaccuracies. The user assumes all risks and liability whatsoever in connection with the use of a product or its applications. JDSU reserves the right to change at any time without notice the design, specifications, function, fit or form of its products described herein, including withdrawal at any time of a product offered for sale herein. JDSU makes no representations that the products herein are free from any intellectual property claims of others. Please contact JDSU for more information. JDSU and the JDSU logo are trademarks of JDS Uniphase Corporation. Other trademarks are the property of their respective holders. © 2005 JDS Uniphase Corporation. All rights reserved. 10143173 500 0707 OCK10.DS.FOP.TM.AE

Test & Measurement Regional Sales

NORTH AMERICA TEL: 1 866 228 3762 FAX: +1 301 353 9216	LATIN AMERICA TEL:+55 11 5503 3800 FAX:+55 11 5505 1598	ASIA PACIFIC TEL:+852 2892 0990 FAX:+852 2892 0770	EMEA TEL:+49 7121 86 2222 FAX:+49 7121 86 1222	WEBSITE:www.jdsu.com
---	--	---	---	-----------------------------